

## PRO5 product change log file

Date	Firmware	Description
2020 11 09	00.06.00.00 build 05.13	<ul style="list-style-type: none"> <li>- Bug fix: react to PDP deactivation; #6964</li> <li>- Bug fix: SSL validation fix; #6922</li> <li>- Feature: BLE parameters for 'info' SMS; #6999</li> <li>- Feature: Device bricking protection; #7070</li> <li>- Feature: Low frequency measurement; #6985</li> <li># Recommended DeviceCenter 0.7.5.xx</li> <li># BLE APP Version 00.B5.02.04</li> </ul>
2020 10 16	00.06.00.00 build 04.33	<ul style="list-style-type: none"> <li>- Bug fix: sim-pin inserting issues; #6839</li> <li>- Bug fix: UART Error 0x8; #6488</li> <li>- Bug fix: transparent channel timeout fix; #6871</li> <li>- Bug fix: AGNSS on 2G without time fix; #6819</li> <li>- Feature: General improvements; #6489</li> <li>- Feature: Technoton DUT-E S7 sensor support; #6204</li> <li>- Feature: Technoton GNOMDDE S7 and GNOMDP S7 sensor support; #6816</li> <li>- Feature: Escort TD BLE sensor support; #6817</li> <li>- Feature: Custom ignition parameter default value improvements; #6968</li> <li># Recommended DeviceCenter 0.7.4.xx</li> <li># BLE APP Version 00.B5.02.04</li> </ul>
2020 09 29	00.06.00.00 build 03.55	<ul style="list-style-type: none"> <li>- Hot fix: Manufacturing improvements; #6854</li> <li># Recommended DeviceCenter 0.7.3.xx</li> <li># BLE APP Version 00.B5.01.10</li> </ul>
2020 09 25	00.06.00.00 build 03.54	<ul style="list-style-type: none"> <li>- Bug fix: modem initialization fix; #6504</li> <li>- Bug fix: M95 gprs attach issue fix; #6550</li> <li>- Bug fix: auto-apn fix; #6584</li> <li>- Bug fix: sensor data preprocess; #6548</li> <li>- Bug fix: ELA sensors incorrect IDs; #6679</li> <li>- Bug fix: EcoPanel misbehaves at startup; #6722</li> <li>- Bug fix: EcoPanel not working when Sleep is disabled; #6704</li> <li>- Bug fix: Network technology switch on the fly fix; #6555</li> <li>- Feature: Business/Private Trip Type; #6401</li> <li>- Feature: multiple firmware update; #6252</li> <li>- Feature: connection rejection response for command 115; #6435</li> <li>- Feature: 1Wire TH sensor integration; #6576</li> <li>- Feature: Accident reconstruction; #5895</li> <li># Recommended DeviceCenter 0.7.3.xx</li> <li># BLE APP Version 00.B5.01.10</li> </ul>

---

2020 09 04 00.06.00.00 build 02.29

- Bug fix: M95 goes offline after losing connection; #6497
  - Bug fix: e-connect issue using auto-apn; #6262
  - Bug fix: AGNSS issue device freezes after receiving a call; #6157
  - Bug fix: Thailand magnetic card reader fix; #6428
  - Bug fix: GSM Operator connection improvements; #6551
  - Feature: camera time sync improvement; #6408
  - Feature: Sensor integrator improvements; #6319
  - Feature: ported geozone ignition and camera time improvements; #6371
- # Recommended DeviceCenter 0.7.2.xx\*;  
# \*xx - minor release version, might change due to hotfixes
- 

2020 08 10 00.06.00.00 build 01.23

- Bug fix: Added missing att commands; #6403
  - Bug fix: gps version code for manufacturing fix; #6448
  - Bug fix: Incorrect Access Technology is shown; #6322
  - Bug fix: UG96 nwscanmode error fixed on cold start; #6299
  - Feature: added new SMS nreset and reconnect; #6264
  - Feature: additional debug from gen4; #6369
- # Recommended DeviceCenter 0.7.1.xx\*;  
# \*xx - minor release version, might change due to hotfixes
- 

2020 07 17 00.06.00.00 build 00.05

- Bug fix: APN provisioning priority issues; #6192
  - Bug fix: Incorrect network technology IO status; #6139
  - Feature: Network technology IO improvements; #6155
  - Bug fix: MIL and DTC code read fix; #6107
  - Bug fix: MB20 autoselect doesn't enable all IOs fix; #5610
  - Feature: Ignore RPM values if angle is greater than set limit; #6032
  - Feature: TCP keepalive 3G support; #6092
- # Recommended DeviceCenter 0.7.0.xx\*;  
# \*xx - minor release version, might change due to hotfixes
- 

2020 07 10 00.05.04.28

- First official release;
- # Recommended DeviceCenter 0.6.4.xx\*;  
# \*xx - minor release version, might change due to hotfixes
-